




M. B. Nigam
Proprietor




PALLAVI BOREWELL & DRILLERS

Dealers in : 6 1/2" 4 1/2" Borewells Drilling & Inwell Drilling

All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.

Moble : 93412 24311, 90089 87530,



Ref :

Date : 15.5.14.....

YIELD REPORT

1. Name and Address of the Party : A E E Ward NO -14 Dasarahalli
Subdivision B R M P.
2. Borewell Location : Sideshwara layout (3rd Cross)
3. Total Depth Drilled : 1148 Feet
4. Casing Pipe : 196 Feet
5. Coupling : 10 Coupling
6. Yield Details :
 - a) First Spring Touched at : 280 Feet
 - b) Second Spring Touched at : 510 Feet
 - c) Third Spring Touched at : 890 Feet
7. Total Yield in G.P.H. : 1200 GPH
8. Remarks : Yield Good

Verf
X.15.14
W4

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

For PALLAVI BOREWELL & DRILLERS

M. B. Miranbary
Proprietor




PALLAVI BOREWELL & DRILLERS

Dealers in : 6 1/2" 4 1/2" Borewells Drilling & Inwell Drilling

All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.

Moble : 93412 24311, 90089 87530,



Ref :

Date : ..15.5.14.....

YIELD REPORT

1. Name and Address of the Party : AEE Gardao / Desarahali
Susomistha B.B.M.P.
2. Borewell Location : Soundarya layout Ath Cent
3. Total Depth Drilled : 1148 Feet
4. Casing Pipe : 196 Feet
5. Coupling : 10 Coupling
6. Yield Details :
 - a) First Spring Touched at : 490 Feet
 - b) Second Spring Touched at : 640 Feet
 - c) Third Spring Touched at : 890 Feet
7. Total Yield in G.P.H. : 1600 G.P.H.
8. Remarks : Good

Verf
K. R. M
14

ಸಹಾಯಕ ಕಾರ್ಯದರ್ಶಿ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

For PALLAVI BOREWELL & DRILLERS

M.B. Anjaney
Proprietor




PALLAVI BOREWELL & DRILLERS

Dealers in : 6 1/2" 4 1/2" Borewells Drilling & Inwell Drilling

All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.

Moble : 93412 24311, 90089 87530,



Ref :

Date : 15.5.14.....

YIELD REPORT

1. Name and Address of the Party : AEE Ward no. 4 Dabarahalli
Sundarabai B.G.M.P.
2. Borewell Location : Soundarya Layout 1st main
(near Bakery)
3. Total Depth Drilled : 1148 Feet
4. Casing Pipe : 196 Feet
5. Coupling : 10 coupler
6. Yield Details :
 - a) First Spring Touched at : 380 Feet
 - b) Second Spring Touched at : 590 Feet
 - c) Third Spring Touched at : 890 Feet
7. Total Yield in G.P.H. : 1400 G.P.H.
8. Remarks : Yield is good

[Signature]
S. A. N. S.
W. 14

ಸಹಾಯಕ ಕಾರ್ಪೊರೇಟರ್ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಾಜ್, ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

For PALLAVI BOREWELL & DRILLERS

M. B. Mirajany
Proprietor

7th point:-

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398



SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

10 to the Assistant Executive Engineer
BBMP
Daguraballi Sub Division -

Date : 7.5.14

1. Name of the Customer

WWS No-14

a) Village 1st Cross (middle)

b) Block / Taluk. N M H Layout

c) District Bangalore

2. Location.

3. Lithology of the Area

Gv Quater (Quartzite) in nature -
The area was a plain area

4. Topographic Features of the Area

Gravelly -

5. Hydrogeological condition of the Area

6. Geophysical survey result.

a) Type of Method.

By Diving method

b) No of Soundings Conducted.

c) Recommended Sounding.

d) Particulars of formations present
in the subsurface/possible ground water
zones encountered at

Approx 70' 11" 2
960-1000'
1150-1180'
2

e) Condition of Ground Water.

7. Type of well Recommended.

8. Depth Recommended.

9. Expected Yield.

10. Quality of Water.

11. Approximate depth at which the water
is expected to be met.

12. Recommended Type and Length of
casing to be inserted.

13. Rain water Harvesting advised or not

14. Remarks.

Site Plan Map



Signature of the consultant

Note :- The Survey was carried out by this diving / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

8th Period -

A. N. CHOWDHARY, M.Sc.,

GEOLOGIST

Phone :
Cell : 98454 73398



SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S.No.:

10th AGE Executive Engineer -

Date : 7.5.14

- | | | | |
|-------------------------|-----------------------------|-------------------|--------------------|
| 1. Name of the Customer | Dagayaballi Jals Division | | |
| a) Village | Ward No. - 14
7 St cross | b) Block / Taluk. | Siddipetara Rayals |
| 2. Location. | | c) District | Bangalore |

3. Lithology of the Area
Granite in the area a plain
4. Topographic Features of the Area
The area is a plain
5. Hydrogeological condition of the Area
Coar -
By Briny nettes
6. Geophysical survey result.

- a) Type of Method.
- b) No of Soundings Conducted.
- c) Recommended Sounding.
- d) Particulars of formations present in the subsurface/possible ground water zones encountered at

e) Condition of Ground Water.

7. Type of well Recommended.
8. Depth Recommended.
9. Expected Yield.
10. Quality of Water.
11. Approximate depth at which the water is expected to be met.

12. Recommended Type and Length of casing to be inserted.
13. Rain water Harvesting advised or not
14. Remarks.

14. Remarks.

1607
X/15/10

Site Plan Map

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

Signature of the consultant

Siddhahalli main Road

not done

Sherry

Keep records paid for Drilling

nearly
 of means
 Spiritly Advices -

4 weeks 30c carriage mail

Costs (6 1/2")
~~950 - 801~~
1800 - 2000 6000

Entered at
 Annual Soc'y.
 560-590
 930-960
 }
 2
 18-14

ಸಹಾಯಕ ಕಾರ್ಯನಾಲ್ಕು ಅಭಿಯಂತರರು

ಜಾಗಲಾಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

11th packet: -

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398



SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

50 the Assistant Executive Engineer
B B M P Date : 7.5.14

1. Name of the Customer

Muns NO. - 14

a) Village

4th B' cross

Sundarya nagar

c) District Bangalore

2. Location.

3. Lithology of the Area

Granitic / Scavistite in nature

4. Topographic Features of the Area

The area is a plain land

5. Hydrogeological condition of the Area

Coar

6. Geophysical survey result.

By Boring method

a) Type of Method.

b) No of Soundings Conducted.

c) Recommended Sounding.

d) Particulars of formations present
in the subsurface/possible ground water
zones encountered at

1 mus 75c'
930 - 970'
1130 - 1160'

e) Condition of Ground Water.

7. Type of well Recommended.

8. Depth Recommended.

9. Expected Yield.

10. Quality of Water.

11. Approximate depth at which the water
is expected to be met.

12. Recommended Type and Length of
casing to be inserted.

13. Rain water Harvesting advised or not

14. Remarks.

RB-14

1st B cross

Recommended
Drilling

ಸಹಾಯಕ ಕಾರ್ಯದರ್ಶಿ ಅಭಿಯಂತರರು

ಬಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ

Site Plan Map

ಬೋಗಸೂರು

1st B cross

Not done

Signature of the consultant

Note :- The Survey was carried out by this diving / Geophysical method of surveying is with our good
knowledge and experience. However no guarantee of water will be given.



A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padmanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

50th the
Habitat - Executive Engineer
B B MP

Date : 7.5.14

1. Name of the Customer

Daradalli Sub Division

a) Village

Ward NO. 14
1st main Road

b) Block / Taluk. Soundarya Nagar

c) District Bangalore

2. Location.

3. Lithology of the Area

Gneiss / Schist in part
The area was a plain area

4. Topographic Features of the Area

5. Hydrogeological condition of the Area

6. Geophysical survey result.

a) Type of Method.

By Boring method

b) No of Soundings Conducted.

c) Recommended Sounding.

d) Particulars of formations present
in the subsurface/possible ground water
zones encountered at

780-830'
1000-1040'
2

e) Condition of Ground Water.

7. Type of well Recommended.

8. Depth Recommended.

9. Expected Yield.

10. Quality of Water.

11. Approximate depth at which the water
is expected to be met.

12. Recommended Type and Length of
casing to be inserted.

13. Rain water Harvesting advised or not

14. Remarks.

RS-14



ಸಹಾಯಕ ಕಾರ್ಖಾನಾ ಅಧಿಕಾರಿಗಳು
ಪದಾಧಿಕಾರಿಗಳು ಉಪ-ವಿಭಾಗ
ಬಾಗಲಾಂಟಿ, ಬಿಜಿಎಂಸಿ
ಬೆಂಗಳೂರು

Approx 600'

Belt 2
Bore hole (6 1/2") -
1000-1050

1100-1300 GPH -
Good -

ನೋಡು 100-110' ಗ ಮೇಲ್ಮೈ
ಮೇಲೆ ಗೆ ನೋಡು
- Shallow advised -

Site Plan Map



Recommended result for
Drilling

Signature of the consultant

Note :- The Survey was carried out by this diving / Geophysical method of surveying is with our good
knowledge and experience. However no guarantee of water will be given.